



# RALLY RACER ALERT

**April 12, 2010**

This Racer Alert is specifically for vehicles that have front mount engines and **lengthwise running driveshafts**. Please attach some kind of a **driveshaft loop** in a location that will assist in supporting a failed drive shaft scenario. This "loop" can be constructed of limit strap material, aluminum, steel, or steel cable. This loop must be firmly attached and allow for full cycle travel of the suspension without interfering with the actual loop. We realize that this precaution is standard measure for today's high performance vehicles. Many, if not most of you, already employ this safety measure. Thank you for your compliance in this matter.